



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

Date: January 13, 2010

Reviewed:

Mine Name: Carr Fork – Pine Canyon	Permit Number: M/045/0004
Operator Name: Kennecott Utah Copper	Inspection Date: December 2, 2009
Inspector(s): L Heppler, Emily Berry	Time: 3:00 pm
Other Participants: Glen Eurick, Zeb Kenyon - Kennecott	Mine Status: Inactive

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Bond Renewal Date: 12-01-2011 **Bond Amount:** \$124,000 **Permit fee** is up to date

Purpose of Inspection: Routine annual Inspection. This site was inspected as a Large mine site on 04/21/2006

Inspection Summary: Mine site had a locked gate on the entrance road, both shaft and portal were secured. No erosional problems were noted. Most of ground disturbance has been reclaimed, including both regrading and revegetation. Revegetation is successful, dominately grasses but also includes biodiversity and locally established conifers. Attached photograph document remaining structures.

Conclusions and Recommendations: OGM to continue annual inspections and monitor the site when in the area.

Inspector's Signature

LAH:vs


cc: Kennecott - Chris Kaiser

O:\M045-Tooele\M0450004-PineCanyonMine\inspections\Insp-12022009.doc


01-20-10



Warehouse



Headframe



Portal



Power building